

CEN24LA118

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site of N14YY (Courtesy of the Federal Aviation Administration)



Photograph 2 - Accident Site of N14YY (Courtesy of the Federal Aviation Administration)



Photograph 3 - Cockpit Rudder Trim Position (Courtesy of the Textron Aviation)



Photograph 3 - Rudder Trim Indicator (Courtesy of the Textron Aviation)