

CEN24LA122

INVESTIGATION PHOTOGRAPHS




Figure 1 - Damaged Engine Mount (Courtesy of FAA)




Figure 2 - Sketch of Accident Location (Courtesy of FAA)