

CEN24LA128

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Tail rotor assembly (Courtesy of FAA)



Photograph 3 - T-bolt installation on exemplar helicopter (Courtesy of NTSB)