

CEN24LA138

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane (Source: Federal Aviation Administration)



Photograph 2 - Right wing damage (Source: Federal Aviation Administration)