



Aaron Sauer
Sr. Air Safety Investigator
Office of Aviation Safety - Central Region

Date: 03/19/24

Subject: CEN24LA138

Contact: FAA Inspector Thurston

According to Inspector Thurston, the airplane impacted the terrain on the left side of the runway after the student pilot lost control on takeoff with crosswind conditions. The on-scene examination of the airplane revealed no mechanical issues. In addition, Inspector Thurston was told by another inspector who spoke with the student pilot, that the student pilot reported that there were no mechanical issues and he lost control on takeoff due to the unexpected wind conditions.

--END OF CONVERSATION--