


[CEN24LA152]

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Engine (Courtesy of FAA)



Photograph 2 - Oil filter and oil adapter - note cut safety wire (Courtesy of FAA)



Photograph 3 - Runway light in wing (Courtesy of FAA)



Photograph 4 - Damage present on outboard end of right wing (Courtesy of FAA)