

CEN24LA156

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Deformation noted to the vertical stabilizer (Courtesy of Airport Manager)



Photograph 2 - Deformation noted to the left and right wings (Courtesy of FAA)