

CEN24LA169

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main wreckage (Source: Federal Aviation Administration)



Photograph 2 - Main wreckage (Source: Federal Aviation Administration)



Photograph 3 - Right main landing gear assembly (Source: Federal Aviation Administration)