

CEN24LA180

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Accident Site (Courtesy of FAA)



Photograph 2 - Accident Site (Courtesy of FAA)



Photograph 3 - Damaged Left Wing (Courtesy of FAA)



Photograph 4 - Interior Fuselage Damage (Courtesy of FAA)