

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA200

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of FAA)



Photograph 2 - Airplane dataplate (Courtesy of FAA)



Photograph 3 - Fuselage damage (Courtesy of FAA)



Photograph 4 - Engine - right side



Photograph 5 - Engine - left side