

CEN24LA207

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Accident site and main wreckage (Source: Cirrus Aircraft)**



**Photograph 2 - Right wing damage (Source: Cirrus Aircraft)**



**Photograph 3 - Engine functional test setup**