

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA208

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane (courtesy of FAA)



Photograph 2 - Impact damage to right wing & fuselage (courtesy of FAA)



Photograph 3 - Accident airplane / site location (courtesy of FAA)



Photograph 4 - Impact damage to engine mount (Courtesy of FAA)