


CEN24LA209

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Holes burned in the bottom of the basket (Courtesy of FAA)



Severed steel
support cable

Photograph 2 - Severed steel support cable (Courtesy of FAA)