

CEN24LA211

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Pilot Photo)



Photograph 2 - Accident Site (Pilot Photo)



Photograph 3 - Engine Cowling (Pilot Photo)




Photograph 4 - Nose Landing Gear Well (FAA Photo)



Photograph 5 - Nose Landing Gear Well (FAA Photo)



Photograph 6 - Engine Oil Pressure Line (Pilot Photo)



Photograph 7 - Engine Oil Pressure Line (Pilot Photo)



Photograph 8 - Engine Oil Pressure Line (Pilot Photo)