

CEN24LA229

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of the front of the airplane at the accident site (courtesy of the Brookings County Sheriff's Office)



Photograph 2 - Aerial view of the left side of the airplane at the accident site (courtesy of the Brookings County Sheriff's Office)



Photograph 3 - Aerial view of the right side of the airplane at the accident site (courtesy of the Brookings County Sheriff's Office)



Photograph 4 - Aerial view of the rear of the airplane at the accident site (courtesy of the Brookings County Sheriff's Office)



Photograph 5 - View of the rear left side of the airplane after it was recovered from the accident site (courtesy of Wilde Air Service LLC)



Photograph 6 - View of the rear right side of the airplane after it was recovered from the accident site (courtesy of Wilde Air Service LLC)



Photograph 7 - View of a feather recovered from the airplane (courtesy of Wilde Air Service LLC)