

CEN24LA233

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Lift Strut Damage (Courtesy of Federal Aviation Administration)