

CEN24LA236

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of Flight School Manager)



Photograph 2 - Right wing root damage (Courtesy of Flight School Manager)



Photograph 3 - Left wing damage (Courtesy of Flight School Manager)



Photograph 4 - Left wingtip damage (Courtesy of Flight School Manager)