

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA266

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of FAA)



Photograph 2 - Empennage Damage (Courtesy of FAA)



Photograph 3 - Vertical Stabilizer Damage (Courtesy of FAA)