

CEN24LA286


INVESTIGATION PHOTOGRAPHS




Photograph 1 - View of the right side of the airplane at the accident site (courtesy of the Federal Aviation Administration)




Photograph 2 - View of the rear of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the engine at the accident site (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the metered pressure test fitting at the accident site, with the protective cap not installed and blue staining present on the fitting (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the metered pressure test fitting at the accident site, with the protective cap not installed and blue staining present on the fitting (courtesy of the Federal Aviation Administration)