

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA288

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Outboard end of left wing (Courtesy of FAA)



Photograph 3 - Left wing inboard to mid-span (Courtesy of FAA)



Photograph 4 - Ground scars on runway (Courtesy of FAA)