

CEN24LA300

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Right Wing and Aileron Substantial Damage (Courtesy of FAA)**



**Photograph 2 - Left Wing Strut Substantial Damage (Courtesy of FAA)**