

Carburetor Icing Probability Graph – CEN24LA301

Airplane: Dendy Tailwind W10

Engine: Lycoming O-320-E2D

Fuel: 100LL

Accident Date: 08/03/2024

Accident Location: West Livingston, TX

Accident Time: 0945 CDT

Weather: Local METAR temperature 78.8° F; dew point 77° F

Source: Federal Aviation Administration
Special Airworthiness Information Bulletin CE-09-35
Carburetor Icing Prevention

