

CEN24LA303

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter at accident site (Courtesy of FAA)



Photograph 2 - Helicopter tail rotor gearbox (Courtesy of FAA)