

CEN24LA306

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Wing Strut Damage (Source - Federal Aviation Administration)



Photograph 2 - Vertical Stabilizer and Rudder Damage (Source - Federal Aviation Administration)