



CEN24LA308

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Alternator Installation at Time of the Accident (Courtesy of the Federal Aviation Administration)



Photograph 2 - Alternator Installation in Accordance with the Cirrus Maintenance Manual Models SR22 and SR22T (Courtesy of Cirrus Aircraft)



Photograph 3: Photo Prior to Engine/Alternator Removal (Courtesy of the Airframe and Powerplant Mechanic)



Photograph 4: Engine Compartment Thermal Damage (Courtesy of the Federal Aviation Administration)



Photograph 5: Damage to Battery (Courtesy of the Federal Aviation Administration)



Photograph 6: Firewall Damage (Courtesy of the Federal Aviation Administration)