

CEN24LA310

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right side fuselage damage (Source: Federal Aviation Administration)



Photograph 2 - Fuselage damage (Source: Federal Aviation Administration)