


CEN24LA318

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the right side of the airplane at the accident site (courtesy of the Michigan State Police)



Photograph 2 - View of the left side of the airplane at the accident site (courtesy of the Michigan State Police)



Photograph 3 - View of the front of the airplane at the accident site (courtesy of the operator)



Photograph 4 - View of the rear of the airplane at the accident site (courtesy of the operator)



**Photograph 5 - View of the substantial damage sustained to the right side of the lower fuselage
(courtesy of the operator)**



**Photograph 6 - View of the substantial damage sustained to the left side of the lower fuselage
(courtesy of the operator)**



**Photograph 7 - View of the substantial damage sustained to the underside of the right wing
(courtesy of the operator)**



**Photograph 8 - View of the substantial damage sustained to the underside of the left wing
(courtesy of the operator)**



Photograph 9 - View of the fuselage with both wings, the landing gear, and the empennage removed (courtesy of the operator)