



Repair Station Certificate: CRS PAZR068H

EAST ALTON

FOD Evaluation – Borescope Report

Customer: FORESHORE CAPITAL

Aircraft: HAWKER 900XP_SN HA-0015

Evaluation Date: 08/2/2024

Aircraft Tail Number: N526FC

Work Order Number: MRT12430

Engine SN: P122137

Aircraft Total Time: 8244.7

Engine Total Times: 8069.3

Aircraft Total Cycles: 4469

Engine Cycles: 4469

Inspector: Celeo Morales

Engine Model: TFE731-50R

Given the nature of borescope instrumentation it is often not possible to make observations and examine all areas of an individual engine as part of an evaluation. Based on this limitation, West Star Aviation, cannot and does not warrant its findings for borescope evaluations (pre-purchase and otherwise) against the possibility that hidden damage may exist that was not observable and reported by our technician at the time of the evaluation.

FOD Evaluation_Borescope Report
CUSTOMER: FORESHORE CAPITAL
AIRCRAFT HAWKER 900XP SN HA-0015



Overview

Performed FOD evaluation of External,
inlet, fan assembly, 1st stage HP
compressor area, LP Turbine and exhaust.



FOD Evaluation Borescope Report
CUSTOMER: FORESHORE CAPITAL AIRCRAFT
HAWKER 900XP SN HA-0015



- External:
Damage noted signs of EMAS ingestion
throughout the engine.



FOD Evaluation Borescope Report
CUSTOMER: FORESHORE CAPITAL
AIRCRAFT HAWKER 900XP SN HA-0015




Stator Vanes Area:
Damage noted signs of EMAS
ingestion throughout the engine.



FOD Evaluation Borescope Report
CUSTOMER: FORESHORE CAPITAL
AIRCRAFT HAWKER 900XP SN HA-0015





Stator Vanes Area:
Damage noted signs of EMAS ingestion
throughout the engine.



FOD Evaluation Borescope Report
CUSTOMER: FORESHORE CAPITAL AIRCRAFT
HAWKER 900XP SN HA-0015




HPC1 Area:
Damage noted signs of EMAS ingestion.



FOD Evaluation Borescope Report
CUSTOMER: FORESHORE CAPITAL
AIRCRAFT HAWKER 900XP SN HA-0015



HPC1 Area:
Damage noted signs of EMAS ingestion.



FOD Evaluation Borescope Report
CUSTOMER: FORESHORE CAPITAL
AIRCRAFT HAWKER 900XP SN HA-0015



LPT & EXHAUST Area:
Damage noted signs of EMAS
ingestion.

