

CEN24LA328

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the airplane at the accident site (courtesy of airport operations)



Photograph 2 - View of the right side of the airplane at the accident site (courtesy of airport operations)



Photograph 3 - View of the left side of the airplane at the accident site (courtesy of airport operations)



Photograph 4 - East facing view of the damage sustained to the engineered material arresting system from the airplane



Photograph 5 - West facing view of the damage sustained to the engineered material arresting system from the airplane



Photograph 6 - View of the front of the airplane on the ramp




Photograph 7 - View of the left side of the airplane on the ramp




Photograph 8 - View of the right side of the airplane on the ramp



Photograph 9 - View of the rear of the airplane on the ramp



Photograph 10 - View of the substantial deformation damage sustained to the frame 5 lower assembly and the lower frame 6 pressing (courtesy of Textron Aviation)



Photograph 11 - View of the substantial deformation damage sustained to the frame 7 lower assembly (courtesy of Textron Aviation)



Photograph 12 - View of the left side of the cockpit



Photograph 13 - View of the right side of the cockpit



Photograph 14 - View of an electronic cockpit display showing the fuel onboard after the accident



Photograph 15 - View of the cockpit voice recorder removed from the airframe