

CEN24LA330

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane on Runway (Courtesy of FAA)



**Photograph 2 - Substantial Damage on Fuselage Adjacent to Left Horizontal Stabilizer
(Courtesy of FAA)**



Photograph 3 - Separated Left Wheel Assembly (Courtesy of FAA)



Photograph 4 - Fractured Left Axle (Courtesy of FAA)