


CEN24LA337

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site (Courtesy of Pilot)



Photograph 2 - Bent engine mount (Courtesy of FAA)



Photograph 3 - Airplane during removal from accident site (Courtesy of Pilot)



Photograph 4 - Airplane after removal from accident site (Courtesy of pilot)