

CEN24LA366

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of the Federal Aviation Administration)



Photograph 2- Damaged Engine Mount (Courtesy of the Federal Aviation Administration)