


CEN24LA350

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Overview (Courtesy of FAA)



Photograph 2 - Venturi and Air Diaphragm (Courtesy of FAA)