

CEN24LA354

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of the Federal Aviation Administration)



Photograph 2 - Number 5 Cylinder (Courtesy of the Federal Aviation Administration)



Photograph 3 - Number 6 Cylinder (Courtesy of the Federal Aviation Administration)



Photograph 4 - Rod End Cap (Courtesy of the Federal Aviation Administration)