



Mitchell Gallo
Senior Air Safety Investigator
Aviation Safety - Central Region

Date: September 23, 2024

Subject: CEN24LA354, Record of Conversation

Contact: Brandon Brasfield, Aviation Safety Inspector, Indianapolis Flight Standards District Office

Brandon Brasfield performed a post-accident examination of N1249D and provided photos of N1249D's engine. He stated the engine had a hole in the crankcase above the No. 6 cylinder assembly. The No. 6 connecting rod was fractured near its base.