

CEN24LA357

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Fuselage Damage (Courtesy of Airport Manager)



Photograph 2 - Fuselage Damage (Courtesy of Airport Manager)



Photograph 3 - Lower Fuselage (Courtesy of Airport Manager)



Photograph 4 - Left Brake Assembly (Courtesy of Kent Picard)



Photograph 5 - Right Brake Assembly (Courtesy of Kent Picard)



Photograph 6 - Skid marks (Courtesy of Airport Manager)