

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA359

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane propeller and nose landing gear damage (Courtesy of FAA)



Photograph 2 - Engine mount (Courtesy of FAA)



Photograph 3 - Composite damage (Courtesy of FAA)