


National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA370

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fuselage damage (Courtesy of FAA)



Photograph 2 - Left wind damage (Courtesy of FAA)



Photograph 3 - Fuel tank interior (Courtesy of FAA)