

CEN25FA281

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (NTSB photo)



Photograph 2 - Fuselage / main rotor blades at accident site (NTSB photo)



Photograph 3 - Fuselage at the accident site (NTSB photo)



Photograph 4 - Fuselage at accident site (NTSB photo)



Photograph 5 - Aft tail boom (NTSB photo)



Photograph 6 - Tail rotor (NTSB photo)



Photograph 7 - Forward landing skid (NTSB photo)