

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN25LA007

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of FAA)



Photograph 2 - Airplane data plate (Courtesy of FAA)



Photograph 3 - Engine test run in progress



Photograph 4 - Engine data plate (Courtesy of Lycoming)



**Photograph 5 - Accident site photo
Upper & lower cowl fairing damage;
spinner & spinner mounting bulkhead damage
(courtesy of FAA)**



Photograph 6 - Spinner interior



Photograph 7 - Spinner exterior; paint transfer mark



Photograph 8 - Spinner exterior; paint transfer mark



Photograph 9 - Spinner exterior; scratches



Photograph 10 - Propeller Blade A - blade face



Photograph 11 - Propeller Blade B - blade face