

CEN25LA015

INVESTIGATION PHOTOGRAPHS



Photograph 1 – Accident site (Courtesy of accident pilot)



Photograph 2 –Fuselage damage (Courtesy of accident pilot)



Photograph 3 – Spar damage (Courtesy of accident pilot)