

CEN25LA018

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Accident site (Courtesy of FAA)



Photograph 3 - Accident site (Courtesy of FAA)



Photograph 4 - Airplane during examination (Courtesy of NTSB)




Photograph 5 - Engine on test rig (Courtesy of NTSB)



Photograph 6 - Air filter, air box, scat duct (Courtesy of NTSB)



Photograph 7 - Collapsed and degraded scat duct (Courtesy of NTSB)



Photograph 8 - Collapsed and degraded scat duct (Courtesy of NTSB)



Photograph 9 - Collapsed and degraded scat duct (Courtesy of NTSB)



Photograph 10 - Collapsed and degraded scat duct (Courtesy of NTSB)



Photograph 11 - Scat duct holes and repairs (Courtesy of NTSB)



Photograph 12 - Scat duct holes and repairs (Courtesy of NTSB)



Photograph 13 - Scat duct holes and repairs (Courtesy of NTSB)