

YEAR 20	DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2024	3/19	64.64		64.04	Replaced radiator fan 5 1. wired. [redacted]
	4/27			64.31	Replaced broken starter armature [redacted]
	5/17			65.61	Performed 5-hour maintenance specified by the XE285 Helicopter ASSEMBLY & OPERATING/MAINTENANCE MANUAL, Section 4. [redacted]
	6/1			66.36	Replaced fan belt NAPA 3VX280 [redacted]
	7/15			69.38	Performed 5-hour maintenance specified by the XE285 Helicopter ASSEMBLY & OPERATING/MAINTENANCE MANUAL, Section 4.5. Fuel Filter NAPA 23595. [redacted]
	10/8			70.36	Removed & Replaced Engine. Replaced shared clutch bolt. Replaced fan belt NAPA 3VX280 [redacted]

YEAR 20	DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10/22				72:47	Replaced control cable. 11/6/24 Performed 5-hour maintenance specified by the XE285 Helicopter ASSEMBLY & OPERATING/MAINTENANCE MANUAL, Section 4.4. Richard W. Campbell Repairman Certificate
11/7				72:47	11/6/24 Performed 25-hour maintenance specified by the XE285 Helicopter ASSEMBLY & OPERATING/MAINTENANCE MANUAL, Section 4.6. Richard W. Campbell Repairman Certificate
11/7				72:51	I certify that this aircraft has been inspected on 11/6/24 in accordance with the scope and detail of part 43, appendix D and was found to be in a condition for safe operation. Total time in service 72:51 Richard W. Campbell Repairman Certificate