

CEN25LA050

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of Airport Manager)



Photograph 2 - Left Wing Damage (Courtesy of Federal Aviation Administration)