

CEN25LA053


INVESTIGATION PHOTOGRAPHS




Photograph 1 - Accident Airplane (Source: Federal Aviation Administration)



Photograph 2 - Ice obstructed engine oil breather tube and alternate air outlet (Source: Recovery Company)



Photograph 3 - Extruded crankshaft oil seal



Photograph 4 - Engine oil breather tube with alternate air outlet and location of engine cowling