

CEN25LA058

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to Airplane (Courtesy of FAA)



Photograph 2 - Airplane Prior to Engine Run