



Aaron Sauer
Sr. Air Safety Investigator
Office of Aviation Safety - Central Region

Date: 01/13/2024

Subject: CEN25LA065

Contact: Aircraft Recovery Company Personnel

According to the aircraft recovery company personnel, the right fuel tank contained 8 gallons of fuel, and the left fuel tank was empty. Neither fuel tank was compromised during the accident.