

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN25LA071

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Airplane at Accident Site, Right Side
(Courtesy of McKinney National Airport Management)**



**Photograph 2 - Airplane at Accident Site, Left Side
(Courtesy of McKinney National Airport Management)**



**Photograph 3 - Engine Mount Tubes
(Courtesy of FAA)**