

CEN25LA083

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Nose Landing Gear Fully Extended and Locked Down (Courtesy of FAA)



Photograph 2 - Substantial Damage to Fuselage (Courtesy of FAA)