

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN25LA095

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane During Postaccident Examination (Courtesy of FAA)



Photograph 2 - Lower Airframe Damage, Left Pilot Position (Courtesy of FAA)



Photograph 3 - Lower Airframe Damage, Right Pilot Position (Courtesy of FAA)